

STEEP TURNS

BASIC STEPS

ROLL, PULL, ADD POWER.
ROLL, PUSH, REMOVE POWER.

AS YOU ROLL, YOU DECREASE VERTICAL LIFT. THEREFORE YOU MUST INCREASE AOA TO HOLD ALT. THIS INDUCES DRAG, THUS YOU MUST INCREASE POWER.

